



Recall Date: November 29, 2016
Recall Number: 17-038

Door Locksets Recalled Due to Risk of Entrapment in an Emergency; Manufactured by Stanley Security Solutions Taiwan

Recall Summary

Name of Product: Door locksets

Hazard: The latches can fail and the door cannot be unlocked from the inside, posing an entrapment risk. This failure could lead to the inability to vacate a location in an emergency.

Remedy: Replace

Consumers should immediately stop using the recalled locksets. For Stanley Commercial Hardware-branded locksets, consumers should contact Stanley Commercial Hardware and for all other brands, consumers should contact Stanley Security Solutions Taiwan to receive a free replacement latch or to schedule an appointment to have the latches replaced free of charge if the lockset is already installed.

Consumer Contact: Stanley Commercial Hardware toll-free at 855-885-1296 from 8 a.m. to 5 p.m. ET Monday through Friday or www.stanleyhardwarefordoors.com and click on Products, then on Recall for more information.

Stanley Security Solutions Taiwan toll-free at 855-655-5750 from 8 a.m. to 5 p.m. ET Monday through Friday or <http://tw.stanleysecuritysolutions.com> and click on Products, then on QCL-100 Recall Notice for more information

Recall Details

Units: About 70,000

Description: This recall involves Stanley’s commercial cylindrical series BMHA/ANSI Grade 1 heavy duty locksets with dead-latch components. The recalled locksets have brass, bronze, nickle, chrome or satin chrome finish. They were sold under 18 different brands and with the following model or part number, located on the packaging:

Brand	Model/Part Number
Advantage	007-FA8990060AD, B48-FC60300B70KD090, B48-FC60301B70KD090, B48-FCO60312B70KD090, B48-FC60351B70KD090 and B48-FCO60302B70KD090
AGI	Y40-FU90300B7000000Y40-, FU90312B7000000 and Y40-FU90362B7000000
Assa Abloy	B67-FCS0300B7000090, B67-FCS0312B7000090, B67-FCS0362B7000090, B67-

	FKS0300B7000090, B67-FKS0300B700009-M, B67-FKS0362B7000090 and B67-FKS0362B700009-M
Cal-Royal	007-FA8990060CR, 313-FL60300B70KD090, 313-FLO60312B70KD090, 313-FL60362B70KD090, 313-FLO60315B70KD090 and 313-FL60361B70KD090
Delaney	Y62-FC90300B70KA090, Y62-FC90362B70KA090 and Y62-FCO60312B70KA09
Dorma	B70-FB30S62B70KD06-B, B70-FL60362B70KD06-B, B70-FL90300B70KD06-B and B70-FLO90312B70KD06-B
Dorex	007-FA8910060DO, 356-FL70300B70KD090, 356-FLO70312B70KD090, 356-FL70361B70KD090 and 356-FL70362B70KD090,
Ecoland	B31-FL60300B70KD000, B31-FL60300B70MK000, B31-FL60362B70KD000, B31-FLO60312B70GK000, B31-FLO60312B70KD000, B31-FR60300B7000000 and B31-FRO60312B7000
General Lock	007-FA8990060GL, B39-FC60300B70KD090, B39-FCO60312B70KD090, B39-FCO60315B70KD090 and B39-FC60362B70KD090
Hager	007-FA891007CHG, 007-FA8910060HG, B33-FL60300B70KD090, B33-FLO60312B70KD090, B33-FLO60315B70KD090, B33-FLO60302B70KD090 and B33-FL60362B70KD090
Hans Johenson	007-FA8910060UC, B26-FC60300B70KD090, B26-FC60362B70KD090, B26-FCO60312B70KD090, B26-FK60300B7000090, B26-FK60362B7000090, 007-FA8910060UC, B26-FCO60315B70KD090 and B26-FKO60312B7000090
Long May	Y23-FL60300B70KD090
MaxGrade	B34-FL60300B70KD090
PowerTek	B49-FT60362B70KD090
Stanley Commercial Hardware	QCL135, QCL150, QCL151, QCL154, QCL155, QCL160, QCL161, QCL168, QCL169, QCL170, QCL171, QCL192, QCL193 and QCL194, QCL195
Taymor	359-FL60362B70KD090
Tell	007-FA8990070UL6, 007-FA8990070UL6, A65-FL70300B70KD09-FA, A65-FLO70315B70KD09-FA, A65-FR70362B700009-FA, 007-FA8990070UL6, A65-FLO70312B70KD09-FA, Y76-FL70300B70KD690, Y76-FL70362B70KD690, Y76-FB30000B70KD690 and A65-FL70362B70KD09-FA
TownSteel	Y87-FL60300B70KD090, Y87-FLO60302B70KD090, Y87-FLO60315B70KD090, Y87-FL60361B70KD090, Y87-FL60362B70KD090

Incidents/Injuries: The firm has received four reports of the latches failing. No injuries have been reported.

Sold at: Stanley Commercial Hardware and other lock distributor and retailers nationwide and online at Amazon.com and Grainger.com from February 2016 through September 2016 for between \$170 and \$320.

Manufacturer: Stanley Security Solutions Taiwan, Ltd. of Taiwan.

Manufactured in: Taiwan

Photos



Recalled lock



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.

About U.S. CPSC:

The U.S. Consumer Product Safety Commission is charged with protecting the public from unreasonable risks of injury or death associated with the use of thousands of types of consumer products under the agency's jurisdiction. Deaths, injuries, and property damage from consumer product incidents cost the nation more than \$1 trillion annually. CPSC is committed to protecting consumers and families from products that pose a fire, electrical, chemical or mechanical hazard. CPSC's work to ensure the safety of consumer products - such as toys, cribs, power tools, cigarette lighters and household chemicals – contributed to a decline in the rate of deaths and injuries associated with consumer products over the past 40 years.

Federal law bars any person from selling products subject to a publicly-announced voluntary recall by a manufacturer or a mandatory recall ordered by the Commission.

To report a dangerous product or a product-related injury go online to www.SaferProducts.gov or call CPSC's Hotline at 800-638-2772 or teletypewriter at 301-595-7054 for the hearing impaired. Consumers can obtain news release and recall information at www.cpsc.gov, on Twitter [@USCPSC](https://twitter.com/USCPSC) or by subscribing to CPSC's [free e-mail newsletters](#).

CPSC Consumer Information Hotline

Contact us at this toll-free number if you have questions about a recall:
800-638-2772 (TTY 301-595-7054)

Times: 8 a.m. – 5:30 p.m. ET; Messages can be left anytime

Call to get product safety and other agency information and to [report unsafe products](#).

Media Contact

Please use the phone numbers below for all media requests.

Phone: 301-504-7908

Spanish: 301-504-7800